



Devil's Slide/Hwy 1
Storm Repair [CLICK HERE](#)



Daily Update
May 13 and 14

Repair Work

Devil's Slide (post mile 39.14)


- Drilling operations continued Saturday and Sunday.



The larger 200T crane in the background was brought in Friday for a longer reach down the cliff.



Clean up work continues in the foreground.



Drill rig and platform about 30 feet below the road.